




MAXLINER

**INSTALLATION
INSTRUCTIONS
MANUAL**

MAXTOP VENTURE WITH DEFOGGER

ISUZU D-MAX DOUBLE CAB 2020+



Contact us



THAILAND OFFICE

☎ +66 38 468 008 ext 2001
✉ info@maxliner.com
🏠 700/135 Moo 5, Amata Nakorn,
Klongtumru, Muang, Chonburi 20000 Thailand










EUROPE OFFICE

☎ +31 8 5020 1887
✉ infoEurope@vandapac.com
🏠 Parallelweg 46 – 48 5121LD Rijen, Netherlands
VAT Identification Number : NL858744272801















AUSTRALIA/OCEANIA OFFICE

☎ +61 1800 592 192
✉ sales@maxliner.com.au
🏠 2 Dexter Drive Epping 3076 VIC Australia

Component parts

 1 1x		 2 1x	
 Type A: <u>R4017160</u>	 Type B: <u>R4017165</u> 3 1x	 4 1x	 5 8x
 6 1x	 7 2x	 8 4x	 9 2x
 10 6x	 11 2x	 12 4x	 13 4x

Tools used

 No.8,10,12,14					
 No.T20,T40	 No.4,5				
 Silicone (Non supply)					




Caution for installation

Read this mounting manual carefully, before your start the installation.


1. Area where to install product should be clean.
2. During installation, person who installed should take off any ornaments.
3. Wear the protective eyewear before installation.

Instruction procedure

With bedliner DC
under rail type




With KD liner DC
under rail type




※ Start the instruction procedure at step 8



With bedliner DC
under rail logo ISUZU type




Without bedliner




1 LH/RH



1.1 (4x)




1.1 (2x)




2

2.1




2.2




Instruction procedure


3 LH/RH




3.1




3.2




4 LH/RH




4.1




4.2




5 LH/RH




5.1



5.2





5.3





Instruction procedure

6

6.1



7 LH/RH





Instruction procedure



8 LH/RH



8.1
(4x)




8.2




9


9.1



9.2






9.3






Instruction procedure



10 LH/RH




11 LH/RH




12



BEWARE OF
CRUSHING HAND





LH/RH






Instruction procedure



13 LH/RH



14




15 LH/RH




Instruction procedure

16 LH/RH

16.1




16.2




17 LH/RH


17.1





17.2



17.3






17.4





18 LH/RH

No.12





Instruction procedure



19 LH/RH



20 LH/RH




21 LH/RH





※ In case installing with harness ③ type A: R4017160 (Type B see on page 24)


22





22.1






22.2




22.3







23.1




23.2




23.3



23.4




23.5




Instruction procedure


24





24.1




24.2




24.3




24.4




24.5




24.6




24.7




24.8







25.1









25.2










25.3








※ CASE INSTALL WITH TRAILER








27.1



27.2





No.14




Instruction procedure


28




28.1




28.2




28.3




28.4




29




29.1








29.2




30







31





31.1




31.2




31.3






31.4




32




Instruction procedure





33.1



33.2



33.3





※ The next procedure are on page 35




Instruction procedure

※ In case installing with harness ③ type B: R4017165

22




23




Instruction procedure


23.2




23.3




23.4




23.5




24




24.1




24.2




24.3







25.1




25.2




25.3




25.4




25.5







26.1









26.2









26.3








※ CASE INSTALL WITH TRAILER




28





28.1




28.2




29




29.1




29.2




29.3




29.4




29.5





29.6




29.7




29.8



29.9




29.10





30

30.1





30.2




Instruction procedure

31

31.1




31.2




32


32.1






32.2



33




Instruction procedure




Instruction procedure

34

34.1




34.2





35


35.1




35.2




35.3



35.4




35.5




36


36.1



36.2




※ Slide in lift up window




Open


1st



2nd



3rd




Close


1st



2nd




3rd







Instruction procedure

37


37.1





37.2 LH/RH






38






39



40




41





※ Adjustment

※ Latch & Striker rear




1.1




1.2 LH/RH


4



Latch & Striker rear





(24x)





※ Latch & Striker rear

1.3



CASE 1 LH/RH




CASE 2 LH/RH




CASE 3 LH/RH





1.4



1.5





※ Latch & Striker side lift up





1.1

CASE 1 LH/RH







CASE 2 LH/RH




※ Latch & Striker side lift up

CASE 3 LH/RH







※ Latch & Striker side slide in lift up






1.1

CASE 1 LH/RH





CASE 2 LH/RH




※ Latch & Striker side slide in lift up


CASE 3 LH/RH





1.2



1.3




※ Sling rear





※ Sling rear


1.1




1.2





1.3




1.4




1.5




※ Side rod




1.1




1.2




1.3



1.4




1.5







※ Side rod



1.6






2





※ Release inside





※ Front window guidelines



※ Front window guidelines




or





LOW




1st



2nd



1st



2nd

